Probable Tornado Echo Bay / Laird Township, Ontario June 6, 2008

Date- Local: Friday, June 6th, 2008

UTC: Friday, June 6th, 2008

Time- Local: 1800

UTC: 2200

Location: Echo Bay / Laird Township **Region:** Sault Ste Marie - Superior East

Classification: Probable Tornado

Category: A Casualties: None

Track Length: 7000 m Width: 200 m

Motion: 210 degrees **Damage Estimate:** \$100 000

F-Scale Rating: F0

Code: MB

Damage Survey: Yes done by Peter Kimbell and Jerry Shields (private meteorologist)

Spotter Reports: None

Other Documents:

Storm damage survey report detailing damage and radar signatures

Photos of damage (open warehouse, near by house) Map of general location and approximate damage path

Tornado F-Scale Assessment

Brad L. Rousseau Tornado Data Production Assistant, Environment Canada March $23^{\rm rd}$, 2010

Classification: Probable Tornado

Date: Friday, June 6th, 2008

Location: Echo Bay / Laird Township, Sault Ste Marie - Superior East Region

Assessment: F0 F-Code: MB

Explanation of Assessment: Partial roof removal from open-faced warehouse; roof damage on neighboring house; damage at nearby arena; sporadic tree damage along

7 km path

SJS

OSPC Storm Damage Survey Report

Investigators Kimbell

Shields (private meteorologist)

Location / Region Echo Bay / Laird Township

Event Date Local / UTC (YYMMDD) 080606

Event Time Local / UTC 2200

Severe Weather Event Type Tornado

Classification Probable

F-scale Value 0

F-scale Code MB

Start Lat / Long 46° 25' / 84° 04'

End Lat / Long unknown

Path Length (m) roughly 7 km (see map)

Motion (degrees) roughly 30

Max. Path Width (m)

Avg. Path Width (m) roughly 150-200

Human Injuries / Fatalities 0

Animal Injuries / Fatalities 0

Damage (\$K) / Source > \$100k (based on newspaper report)

Damage Description partial roof removal from open-faced warehouse; roof

damage on neighbouring house; damage at neaby arena; sporadic tree damage along 7 km path (see

map)

Other Notes No survey undertaken; details received from Jerry

Shields, who runs his own weather web-site (shieldsweather.com). Small hook visible on 2230Z Cappi. Only very weak Doppler velocity couplet

visible (not conclusive).

Images and Captions below
















Important notes from this isolated storm:

- Hail size reported to be ~ 2.5 inches in diameter, both reported by Vic Fremlin and the Sault newspaper.
 - (http://www.saultstar.com/ArticleDisplay.aspx?e=1064372&auth=Corina+Milic or http://www.sootoday.com/content/news/full_story.asp?StoryNumber=32576)
- Tom Fremlin (Vic's brother) took picture(s), but I could not get a hold of him. Vic can be reached at 705-256-0496 and Tom can be reached at 705-255-0885
- Evidence of F0 damage from photos; however, since a roof was torn off it is possible that this was F1 damage.
- Trees were down on the property of Vic Fremlin, plus damage to equipment and the building.



Environnement Canada

[Français] [Back]

V	iew	Ev	ent

Back To Search Results

Event start date 2008-6-6 UTC (exact) Event start date 22:00-00 UTC (exact) Event duration 00:05:00 (rough) Entered by rodgersd (2008-06-27 16:34:51) Event version latest first region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - SUPERIOR EAST meso region 00 NM N of Echo Bay Hail yes location 00 NM N of Echo Bay Hail is ze descriptor N/A Hail diameter 2.5 inches (measured) Hail diameter 2.5 inches (measured) Hail diameter 2.5 inches (measured) Hail diameter 3.7 inches (measured) Hail diameter 3.8 inches (measured) Hail diameter 3.9 inches (measured) Hail diameter 3.0 inches (measured) Hail diameter 4.0 inches (measured) Hail diameter 5.0 inches (measured) Hail diameter 8.0 inches (measured) Hail diameter 9.0 inches (measured) Hail diame	View Event	Back To Search Results	
Event start time	Event type	Tornado (vetted)	
Event duration 00:05:00 (rough) Entered by Fodgersd (2008-06-27 16:34:51) Event version latest fest region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - ST. JOSEPH ISLAND Latitude/Longitude 46 ° 29' N 84 ° 4' W Location 0 KM N of Echo Bay Hall Ste descriptor N/A Location N/A Mill diameter 2.5 inches (measured) Hall diameter 2.5 inches (measured) Hall diameter 2.5 inches (measured) Hall diameter N/A Mill diameter N	Event start date	2008-6-6 UTC (exact)	
Entered by Event version Event version Exter region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - ST. JOSEPH ISLAND Latitude/Longitude 46 * 29' N 84 * 4' W Location O KM N of Echo Bay Hall Hall size descriptor N/A Hall diameter 2.5 inches (measured) Hall depth N/A Mind no Gust speed N/A Mind direction N/A Mind direction N/A Mind intensity N/A Rain amount N/A Rain duration N/A Tormado yes Lightning Intensity N/A Mesocyclone Funnel Cloud no Waterspout Roof torm off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off), Hall reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hall shape was odd; looked like an "egg in a fiving pari". 3/4 of the ground was covered with hall. High winds seemed to "cut" the long grass at the dealership and the war all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence Public MSC initiated report of event N/A Contact name Ver Fremin Contact phone Tob-256-0496 Contact email N/A Number of fatalities N/A Number of finjuries N/A Ningher of injuries N/A	Event start time	22:00:00 UTC (exact)	
Event version latest fest region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - ST. JOSEPH ISLAND Latitude/Longitude 46 ° 29 N 84 ° 4 ° W Location 0 KM N of Echo Bay Hall was been supported by the support of support o	Event duration	00:05:00 (rough)	
fest region SAULT STE. MARIE - SUPERIOR EAST meso region SAULT STE. MARIE - ST. JOSEPH ISLAND Latitude/Longitude 46 * 29 * N 84 * 4* W Location 0 KM N of Echo Bay Hail size descriptor N/A Hail diameter 2.5 inches (measured) Hail depth N/A Wind no Gust speed N/A Wind direction N/A Rain mount N/A Rain mount N/A Rain dration Tomado yes Tomado intensity Fo (estimated) Lightning linensity N/A Mesocyclone no Funnel Cloud no Roof form off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported, mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an 'eggi in a flying pan'. 34 of the ground was seen about 1/2 mile away. Confidence Funce Confidence Public MSC initiated report of event Vice Fremin Contact phone Tomado N/A N/A N/A Number of flatalities N/A Number of figuries N/A Number of figuries N/A Number of injuries N/A	Entered by	rodgersd (2008-06-27 16:34:51)	
meso region SAULT STE. MARIE - ST. JOSEPH ISLAND Latitude/Longitude 46 ° 29 N 84 ° 4' W Location 0 KM N of Echo Bay Hail yes Hail size descriptor N/A Hail diameter 2.5 inches (measured) Hail depth N/A Wind no Gust speed N/A Wind direction N/A Wind direction N/A Wind intensity N/A Rain amount N/A Rain duration Tornado yes Tornado yes Tornado intensity Lightning Intensity N/A Mesocyclone Founder Island Roof tom off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprotoded or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a flying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence Warning Criteria met or exceeded Source Public MSC initiated report of even! N/A Number of injuries N/A Number of injuries N/A Nimber of injuries N/A	Event version	latest	
Latitude/Longitude 46 ° 29' N 84 ° 4' W Location	fcst region	SAULT STE. MARIE - SUPERIOR EAST	
Location D KM N of Echo Bay Hall yes Hall size descriptor N/A Hall diameter 2.5 inches (measured) Hall diamete	meso region	SAULT STE. MARIE - ST. JOSEPH ISLAND	
Hail size descriptor N/A Hail diameter 2.5 inches (measured) Hail depth N/A Wind no Gust speed N/A Wind direction N/A Wind intensity N/A Rain mount N/A Rain amount N/A Rain duration N/A Tomado yes Lightning litensity N/A Mesocyclone no Funnel Cloud no Waterspout no Rarative Roof for no ff one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uproted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter	Latitude/Longitude	46 ° 29' N 84 ° 4' W	
Hall diameter	Location		
Hail depth N/A Wind no Gust speed Ni/A Wind direction Ni/A Wind direction Ni/A Wind intensity Ni/A Rain no Rain amount Ni/A Rain duration Ni/A Tornado yes Tornado intensity F0 (estimated) Lightning litensity Ni/A Mesocyclone no Funnel Cloud no Waterspout no Roft forn off one building at tractor dealership (Northshore Tractor Ltd), Several trees damaged (either uprooted or tops ripped off), Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding, An ominous black cloud was seen about 1/2 mile away. Confidence probable MSC initiated report of event Ni/A MSC initiated report of event Ni/A Number of fatalities Ni/A Number of fatalities Ni/A Number of injuries Ni/A Number of injuries Ni/A Nimber of injuries Ni/A	Hail		
Hail depth NI/A Wind no Gust speed NI/A Wind direction NI/A Wind intensity NI/A Rain no Rain amount NI/A Rain duration NI/A Tornado Yes Lightning Intensity NI/A Mesocyclone no Funnel Cloud no Waterspout Roof tom off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact phone 705-256-0496 Contact address N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Number of injuries N/A Nimber of injuries N/A Nimber of injuries N/A Nimber of injuries N/A	Hail size descriptor		
Wind no Gust speed N/A Wind direction N/A Wind intensity N/A Rain mount N/A Rain duration N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning thensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An orninous black cloud was seen about 1/2 mile away. Confidence probable Morning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact address N/A Number of fatalities N/A Number of injuries N/A	Hail diameter		
Gust speed N/A Wind direction N/A Wind intensity N/A Rain no Rain amount N/A Rain no Rain amount N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning thensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd), Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter thail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding, An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact address N/A Number of fatalities N/A Number of injuries N/A	Hail depth		
Wind direction N/A Wind intensity N/A Rain no Rain amount N/A Rain mount N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying parn". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and three mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact drains N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Number of injuries N/A Ninjury comments	Wind	no	
Wind direction N/A Wind intensity N/A Rain no Rain amount N/A Rain mount N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying parn". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and three mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact drains N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Number of injuries N/A Ninjury comments	Gust speed	N/A	
Wind intensity N/A Rain no Rain amount N/A Rain duration N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof tom off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported, mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event Contact name Vic Fremlin Contact phone 705-256-0496 Contact ddress N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Injury comments			
Rain nount N/A Rain amount N/A Rain duration N/A Rain duration N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported, mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact address N/A Number of fatalities N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Nimber of injuries N/A			
Rain amount N/A Rain duration N/A Rain duration N/A Tornado yes Tornado intensity F0 (estimated) Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source public MSC initiated report of event N/A Contact name Vc Fremlin Contact phone 705-256-0496 Contact email N/A Number of fatalities N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Number of injuries N/A Nimber of injuries N/A	Rain		
Rain duration NI/A Tomado yes Tomado intensity F0 (estimated) Lightning yes Lightning Intensity NI/A Mesocyclone no Funnel Cloud no Waterspout no Roof tom off one building at tractor dealership (Northshore Tractor Ltd), Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls, Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event NI/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email NI/A Number of fatalities NI/A Number of fatalities NI/A Number of injuries NI/A Number of injuries NI/A Number of injuries NI/A Ni/A Ni/A Ni/A Ni/A Ni/A Ni/A Ni/A Ni			
Tomado yes Tomado intensity F0 (estimated) Lightning yes Lightning Intensity NI/A Mesocyclone no Funnel Cloud no Waterspout Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event NI/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email NI/A Number of fatalities NI/A Number of fatalities NI/A Number of injuries NI/A Number of injuries NI/A N	Rain duration		
Tomado intensity F0 (estimated) Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof tom off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Number of fatalities N/A Fatality comments N/A Number of injuries N/A Injury comments N/A	Tornado		
Lightning yes Lightning Intensity N/A Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vc Fremlin Contact phone 705-256-0496 Contact email N/A Number of fatalities N/A Number of fatalities N/A Number of injuries N/A Nijniyr comments N/A	Tornado intensity	<u>-</u>	
Lightning Intensity Mesocyclone Funnel Cloud No Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Number of fatalities N/A Number of fatalities N/A Number of injuries N/A Injury comments N/A			
Mesocyclone no Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Number of fatalities N/A Number of fatalities N/A Number of injuries N/A			
Funnel Cloud no Waterspout no Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A			
Waterspout Roof torn off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence			
Roof tom off one building at tractor dealership (Northshore Tractor Ltd). Several trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2 mile away. Confidence probable Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Contact address N/A Number of fatalities N/A Number of injuries N/A Number of injuries N/A Injury comments N/A			
Warning Criteria met or exceeded Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Contact address N/A Number of fatalities N/A Number of injuries N/A Injury comments N/A		trees damaged (either uprooted or tops ripped off). Hail reported; mostly 2.5 inches diameter but some were said to be as large as 3 inches diameter. Hail shape was odd; looked like an "egg in a frying pan". 3/4 of the ground was covered with hail. High winds seemed to "cut" the long grass at the dealership and threw mud all over the building walls. Damage to siding. An ominous black cloud was seen about 1/2	
Source Public MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Contact address N/A Number of fatalities N/A Number of injuries N/A Injury comments N/A	Confidence	probable	
MSC initiated report of event N/A Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Contact address N/A Number of fatalities N/A Number of injuries N/A Injury comments N/A	Warning Criteria	met or exceeded	
Contact name Vic Fremlin Contact phone 705-256-0496 Contact email N/A Contact address N/A Number of fatalities N/A Number of injuries N/A Injury comments N/A	Source	Public	
Contact phone 705-256-0496 Contact email N/A Contact address N/A Number of fatalities N/A Fatality comments N/A Number of injuries N/A Injury comments N/A	MSC initiated report of event	N/A	
Contact email N/A Contact address N/A Number of fatalities N/A Fatality comments N/A Number of injuries N/A Injury comments N/A	Contact name	Vic Fremlin	
Contact address N/A Number of fatalities N/A Fatality comments N/A Number of injuries N/A Injury comments N/A	Contact phone	705-256-0496	
Number of fatalities N/A Fatality comments N/A Number of injuries N/A Injury comments N/A	Contact email	N/A	
Fatality comments N/A Number of injuries N/A Injury comments N/A	Contact address	N/A	
Number of injuries N/A Injury comments N/A	Number of fatalities	N/A	
Injury comments N/A	Fatality comments	N/A	
	Number of injuries	N/A	
Damage amount 200	Injury comments	N/A	
	Damage amount	200	

Damage comments	This amount was estimated by the co-owner of Northshore Tractor Ltd. and pertains only to his business
Power outage	N/A .

Back To Search Results

Note: Event details are highlighted in orange.

You've Logged On As user: sillsd (ONT)

Today is: 2010-03-23

Account expiry date: 2014-12-31

Logoff

[Graphics off] |

Important Notices and Disclaimers

Created: 2003-12-08 Modified: 2006-02-16 Reviewed: 2003-12-08

Url of this page: http://performance.ec.gc.ca/eventdata/viewevent_e.php?b_templatePrint=true

The Green LaneTM, Environment Canada's World Wide Web Site. Canada

:XJAT2

OFFENDING COMMAND: timeout